



9520 10th Ave S Ste 150
Seattle, WA 98108
Phone: (206) 607-3000
Fax: (206) 607-3001
www.nrcc.com

Emergency Response
1-800-899-4672

September 6, 2018

Mr. Joseph Gilliam
Environmental Engineering and Technology Section U.S. Army
4735 E Marginal Way S
Seattle, WA 98134

Re: **Report of Activities for Leaking Drum**
2801 SW Florida St
Seattle, WA 98106
NRC Job # 129806

Dear Mr. Gilliam,

The following correspondence details the results of activities conducted by NRC Environmental Services (NRC) on August 21, 2018 for Environmental Engineering and Technology Section U.S. Army at 2801 SW Florida St in Seattle, WA.

Initial Activities

On August 21, 2018, NRC personnel responded to the above-mentioned address to assess and clean the impacts of a leaking drum. Upon arrival, with appropriate PPE, NRC personnel assessed the site and found a 55-gallon drum that had leaked onto a containment pallet and was empty. NRC personnel removed the leaking drum and placed it into an 85-gallon overpack drum. The impacted water/oil from the containment was then pumped into the overpack drum. NRC personnel utilized a biodegradable detergent and rags to remove the remaining residual impacts from the containment pallet. The overpack drum was then secured, labeled, and left on site as directed.

Recommendations

NRC personnel does not recommend any further actions at this time.

Copies of photos of cleanup activities are included with this report. All work performed by NRC was in strict compliance with all local, state and federal regulations, with a special emphasis placed on safety and protection to the environment.

Respectfully,

Roman Geigle

Roman Geigle

Response Supervisor

NRC Environmental Services

Desk: 503-283-1150

E-mail: rgeigle@nrcc.com

Cell: 503-522-2473

EXCELLENCE IN ENVIRONMENTAL & EMERGENCY SOLUTIONS

NRC 9520 10th AVE S Suite 150, Seattle, WA 98108 +1 206 607 3000

www.nrcc.com

Photo Documentation



Photo 1: Site upon arrival.



Photo 2: NRC personnel pumping oil/water from containment pallet.



Photo 3: NRC personnel removing residual impacts from pallet.



Photo 4: Site upon completion.